

# Inspection Report

This report is created by

**LAUNCH**

---

## Vehicle Information

**VIN:** SALWA2JE1GA

**Vehicle manufacturer/model:** Landrover/New Range Rover Sport

**Year of manufacture:** 2016

**Odometer:** 98157

**Vehicle Software Version:** V35.10

---

## Inspection Organization

**Name:** BigJimny Services Ltd

**Address:** 158, Nine Mile Ride, Finchampstead, Wokingham, RG40 4JA

**Contact Number:** [+447535744972](tel:+447535744972)

**SN:** 979628047085

**Time and date of inspection:** 2026-03-15 12:16:31

---

## Inspection Result

**There are 7 issues for Vehicle body system:**

- 1.Pressure Increases Too Slow When Filling Reservoir.
- 2.Invalid Data Received From Ride Level Control Module
- 3.Windshield Misting Sensor
- 4.Rear Right Turn Signal
- 5.Central Configuration
- 6.Control Module Output Power A
- 7.High Speed CAN Communication Bus

**Inspections are normal for Vehicle body system**

- 1.CAV (Connect And View Module)
- 2.SPMA (Safety Belt Pretensioner Control Module A - Drivers Side)
- 3.TPM (Tire Pressure Monitor Module)
- 4.DRDM (Driver's (Side) Rear Door Module)
- 5.GSM (Gear Shift Module)
- 6.RDCM (Rear Differential Control Module)
- 7.DSM (Driver's Seat Module)
- 8.PAM (Parking Assist Control Module)
- 9.TCU (Telematic Control Unit Module)
- 10.ATCM (All Terrain Control Module)
- 11.ECM (Engine Control Module)
- 12.SRS (Supplemental Inflatable Restraint System)

- 13.PBM (Parking Brake Control Module)
- 14.CHCMB (Chassis Control Module B)
- 15.TCCM (Transfer Case Control Module)
- 16.RGTM (Rear Gate/trunk Module)
- 17.DDM (Driver's Door Module)
- 18.PRDM (Passenger's (Side) Rear Door Module)
- 19.PSCM (Power Steering Control Module)
- 20.SASM (Steering Angle Sensor Module)
- 21.FCIMC (Front Controls Interface Module C(Front Audio Control Panel))
- 22.RFA (Keyless Vehicle Module)
- 23.AAM (Audio Amplifier Module)
- 24.PSM (Passenger's Seat Module)
- 25.TVM (Television Module)
- 26.GWM (Gateway Module)
- 27.FCDIM (Front Control/display Interface Module(High Level Display Front))
- 28.FCIM (Front Controls Interface Module(Heating Ventilation Air Conditioning Controls))
- 29.RHVAC (Rear Heating Ventilation And Air Conditioning Control Module)
- 30.IPC (Instrument Cluster Control Module)
- 31.PDM (Passenger's Door Module)
- 32.DABM (Digital Audio Broadcast Module)
- 33.SPMB (Safety Belt Pretensioner Control Module B - Passengers Side)
- 34.TCM (Transmission Control Module)
- 35.IPMA (Image Processing Control Module A)
- 36.FCIMB (Front Controls Interface Module B(Front Audio Control Panel))
- 37.IPMB (Image Processing Module B)

## Professional Report

---

<b>CAV (Connect And View Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>SPMA (Safety Belt Pretensioner Control Module A - Drivers Side)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>TPM (Tire Pressure Monitor Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>DRDM (Driver's (Side) Rear Door Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>GSM (Gear Shift Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>RDCM (Rear Differential Control Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>DSM (Driver's Seat Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>PAM (Parking Assist Control Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>TCU (Telematic Control Unit Module)</b>	Normal <span style="font-size: 1em;">▼</span>
<b>ATCM (All Terrain Control Module)</b>	Normal <span style="font-size: 1em;">▼</span>

**CHCM (Chassis Control Module)**

Abnormal 1 ^

**DTC Qty (1)**

C1A20-64

Pressure Increases Too Slow When Filling Reservoir.

Permanent

**ECM (Engine Control Module)**

Normal v

**SRS (Supplemental Inflatable Restraint System)**

Normal v

**CCM (Speed Control Module)**

Abnormal 1 ^

**DTC Qty (1)**

U0421-81

Invalid Data Received From Ride Level Control Module

Permanent

**HVAC (Heating Ventilation And Air Conditioning Control Module)**

Abnormal 1 ^

**DTC Qty (1)**

B13C2-49

Windshield Misting Sensor

Permanent

**PBM (Parking Brake Control Module)**

Normal v

**CHCMB (Chassis Control Module B)**

Normal v

**TCCM (Transfer Case Control Module)**

Normal v

**RGTM (Rear Gate/trunk Module)**

Normal v

**DDM (Driver's Door Module)**

Normal v

**PRDM (Passenger's (Side) Rear Door Module)**

Normal v

**PSCM (Power Steering Control Module)**

Normal v

**SASM (Steering Angle Sensor Module)**

Normal v

**FCIMC (Front Controls Interface Module C(Front Audio Control Panel))**

Normal v

**RFA (Keyless Vehicle Module)**

Normal v

**AAM (Audio Amplifier Module)**

Normal v

<b>PSM (Passenger's Seat Module)</b>	Normal	∨
<b>TVM (Television Module)</b>	Normal	∨
<b>GWM (Gateway Module)</b>	Normal	∨
<b>BCM (Body Control Module)</b>	Abnormal	2 ^
<b>DTC Qty (2)</b>		
B1248-15	Rear Right Turn Signal	Permanent
U2300-54	Central Configuration	Permanent
<b>FCDIM (Front Control/display Interface Module(High Level Display Front))</b>	Normal	∨
<b>FCIM (Front Controls Interface Module(Heating Ventilation Air Conditioning Controls))</b>	Normal	∨
<b>RHVAC (Rear Heating Ventilation And Air Conditioning Control Module)</b>	Normal	∨
<b>IPC (Instrument Cluster Control Module)</b>	Normal	∨
<b>PDM (Passenger's Door Module)</b>	Normal	∨
<b>DABM (Digital Audio Broadcast Module)</b>	Normal	∨
<b>ACM (Audio Front Control Module)</b>	Abnormal	1 ^
<b>DTC Qty (1)</b>		
U200D-11	Control Module Output Power A	Permanent
<b>SPMB (Safety Belt Pretensioner Control Module B - Passengers Side)</b>	Normal	∨
<b>ABS (Anti-lock Braking System)</b>	Abnormal	1 ^
<b>DTC Qty (1)</b>		
U0001-81	High Speed CAN Communication Bus	Permanent
<b>TCM (Transmission Control Module)</b>	Normal	∨

**IPMA (Image Processing Control Module A)**

Normal ▾

**FCIMB (Front Controls Interface Module B(Front Audio Control Panel))**

Normal ▾

**IPMB (Image Processing Module B)**

Normal ▾

---

## Disclaimer

---

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.