

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: JSAFJB43V

Vehicle manufacturer/model: Suzuki/

Year of manufacture:

Vehicle Software Version: V39.10

Inspection Organization

Name: BigJimny Services Ltd

Address: 158, Nine Mile Ride, Finchampstead, Wokingham, RG40 4JA

Contact Number: [+447535744972](tel:+447535744972)

SN: 979628047085

Time and date of inspection: 2026-03-11 12:16:33

Inspection Result

There are 4 issues for Vehicle body system :

- 1.Right Front Tire Pressure Low
- 2.Left Front Tire Pressure Low
- 3.Right Rear Tire Pressure Low
- 4.Left Rear Tire Pressure Low

Inspections are normal for Vehicle body system

- 1.Supplemental Inflatable Restraint System (SRS)
- 2.Transmission Control Module (TCM)
- 3.Engine Control Module (ECM)
- 4.Anti-Lock Braking System (ABS)
- 5.Instrument Cluster (IC)

Professional Report

Supplemental Inflatable Restraint System (SRS)	Normal	∨
Transmission Control Module (TCM)	Normal	∨
Tire Pressure Monitoring System (TPMS)	Abnormal	4 ^

DTC Qty (4)

B1A30	Right Front Tire Pressure Low	History
B1A31	Left Front Tire Pressure Low	History
B1A32	Right Rear Tire Pressure Low	History
B1A33	Left Rear Tire Pressure Low	History
Engine Control Module (ECM)		Normal ▾
Anti-Lock Braking System (ABS)		Normal ▾
Instrument Cluster (IC)		Normal ▾

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.