

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: JSAHJB74B

Vehicle manufacturer/model: Suzuki/

Year of manufacture:

Vehicle Software Version: V39.10

Inspection Organization

Name: BigJimny Services Ltd

Address: 158, Nine Mile Ride, Finchampstead, Wokingham, RG40 4JA

Contact Number: [+447535744972](tel:+447535744972)

SN: 979628047085

Time and date of inspection: 2026-03-11 12:00:10

Inspection Result

There are 1 issues for Vehicle body system:

1.CAN Invalid Data From ABS / ESP Control Module

Inspections are normal for Vehicle body system

- 1.Tire Pressure Monitoring System (TPMS)
- 2.Body Control Module (BCM)
- 3.4 Wheel Drive (4WD)
- 4.Electronic Power Steering (EPS)
- 5.Anti-Lock Braking System (ABS)
- 6.Central Gateway Control Module (CGW)
- 7.Engine Control Module (ECM)
- 8.Instrument Cluster (IC)
- 9.Emergency Call (TCU)
- 10.Supplemental Inflatable Restraint System (SRS)
- 11.Dual Sensor Brake Support (MFL)

Professional Report

Tire Pressure Monitoring System (TPMS)

Normal

Body Control Module (BCM)

Normal

4 Wheel Drive (4WD)	Normal	∨
Electronic Power Steering (EPS)	Normal	∨
Anti-Lock Braking System (ABS)	Normal	∨
Central Gateway Control Module (CGW)	Normal	∨
Lighting And Turn Signal (CSW)	Abnormal	1 ∨
Engine Control Module (ECM)	Normal	∨
Instrument Cluster (IC)	Normal	∨
Emergency Call (TCU)	Normal	∨
Supplemental Inflatable Restraint System (SRS)	Normal	∨
Dual Sensor Brake Support (MFL)	Normal	∨

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.