

# Inspection Report

This report is created by

**LAUNCH**

---

## Vehicle Information

**VIN:** JSAFJB43V

**Vehicle manufacturer/model:** Suzuki/

**Year of manufacture:**

**Vehicle Software Version:** V39.10

---

## Inspection Organization

**Name:** BigJimny Services Ltd

**Address:** 158, Nine Mile Ride, Finchampstead, Wokingham, RG40 4JA

**Contact Number:** [+447535744972](tel:+447535744972)

**SN:** 979628047085

**Time and date of inspection:** 2026-03-11 12:24:39

---

## Inspection Result

**Inspections are normal for Vehicle body system**

- 1.Immobilizer (IMMO)
- 2.Engine Control Module (ECM)
- 3.Supplemental Inflatable Restraint System (SRS)

---

## Professional Report

<b>Immobilizer (IMMO)</b>	Normal <input type="checkbox"/>
<b>Engine Control Module (ECM)</b>	Normal <input type="checkbox"/>
<b>Supplemental Inflatable Restraint System (SRS)</b>	Normal <input type="checkbox"/>

---

## Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.